Work Order ID 60443 Wednesday, July 07, 2010 3:25:43 PM	1				SHIP	15 Pers 1
tem ID: D900-619-011 Revision ID: tem Name: Bearpaw Start Date: 7/8/2010 Start C Required Date: 7/15/2010 Req'd Reference:	Qty: 1.00 Qty: 4.003	IP4	Cust Item II	IIII IIII IIII III		Stop
Approvals: Process Plan:QC:	Date: 10-7-		Da Da	te:		Stop
Sequence ID/ Operat Work Center ID Descrip		Set Up/ Run Hours	Tool ID	Tool # Plan Code	Accept Reject Qty Qty	Reject Insp. Number Stamp
Draw Nbr Revision Nb IIN-D900-619 A	or		!	-10 40 10	1	
100 IIIII IIIIIIIIIIIIIIIIIIIIIIIIIIIII	Memo Photocopy bluefile &type labels per CHG003	0.00 0.00 r PPP D900-619-011	volus/34		Afor I	BG 10/07/29
Pick Kit Packaging Packaging	Мето	0.00			147/29	334
20 QC4-10	0% Inspect kits for completeness	0.00	W-129		42	 -
QC Quality Control	Memo	0.00	w			

Work	Order	ID	60443
T T O I IX	Oiuci	11/	VVTT

Wednesday, July 07, 2010 3:25:43 PM



Page 2

Item ID:

D900-619-011

Accept

Accept

Qty

Setup Start



Revision ID:

Start Date:

Item Name:

Bearpaw

7/8/2010

Required Date: 7/15/2010

Start Qty: 4.00

Operation

Description

Req'd Qty: 4.00

Cust Item ID: Customer:

Tool ID

Reference:

Approvals:

Process Plan: ____ Date: ___

Date:

Tooling:

SPC (Y/N):

Set Up/

Run Hours

Date:

Date:

Tool # Plan

Code

Sequence ID/

Work Center ID

Packaging

Packaging

Memo

0.00

0.00

Identify and pack for shipping as per PPP D900-619-011

Location:

140

QC

Quality Control

QC21- Final Inspection - Work Order Release

0.00

Memo

0.00

Run

Qty

Start

Stop

Stop

Insp. Reject

Reject Number Stamp

, Picklist Print													
Wednesday, July 07,	2010 3:25:42 PM	1					Ĭ						Page
Work Order ID: 604	443									-			+
Parent Item: D9	00-619-011				• • • • • • • • • • • • • • • • • • •								:
Parent Item Name:	Bearpaw		1100					ę.	tart Data	7/8/2010	D	15 . 50	, , ' ', '', '', '', '', '', '', '', '', '
									Start Qty:	i .		ed Date: 7/1 red Qty: 4.0	
	IPP .C\(\partial\) 04.02.1 IPP Rev:D Was I IPP Rev:E New M	7□Blank size char k10010 07-01- Manufacturing Met	-03 JLI	М							, l	ieu Qiy. 4.0	
Component Item ID/ Item Name	Replacement Item ID		Bin	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per	Kit Total Qty	Qty Issued	Date Issued	Status
AN4-15A		Purchased	No			110	Each	387.0000	8	10/7/29	0		
Bolt				Location	<u>n</u>	Loc (Otv	Loc Code					- 1-2
	•			ST358	_		387	Est Cout			į.		!
1		,			114784		87 300			(b)	- [1
AN960JD416	NAS1149D0463J	Purchased	No		113100	110	Each	12.0000	18	13224	_ :	1 1	1
										MIISO	20 //	11/20	
Washer						1			1100111201	111130		11/04.	SP.
			•	Location ST351	1	Loc (Loc Code					
Pa				31301	108827		12 12	•					at
D2182B Rubber Cushion		Manufactured	No		c	110	f	254.3952	2	10/7	129 5	P (32)
Ы				Location	. *.	Loc (<u>Oty</u>	Loc Code				_	
9	0			ST402A			9.67				_		
	mensurd's			ST410	30872		9.67				-		1
(D2182B060) cut 4 at 6.00	7" Stolvo-125 0" as per dwg per kit			31410	52649	244.7 244.7					- i - :		
					,								
I							ļ						
							-						

Dart Aerospace Ltd W/O: WORK ORDER CHANGES Approval Chief Eng / **Approval** STEP DATE PROCEDURE CHANGE Bv Qtv Date QC Inspector Prod Mar Part No: PAR #: _____ Fault Category: _____ NCR: Yes No DQA: ____ Date: ____ Disposition: _____ QA: N/C Closed: _____ Date: ____ Resolution: **WORK ORDER NON-CONFORMANCE (NCR)** NCR: **Corrective Action** Section B Verification Description of NC **Approval Approval** DATE **STEP** Sign & **Action Description** Initial Section A QC Inspector Section C Chief Eng Date Chief Eng Chief Ena

NOTE: Date & initial all entries

H:\fFGRMS\Quality Assurance\approved QA\NCRWO RevE

Picklist Print

Wednesday, July 07, 2010 3:25:42 PM

Page 2

110

110

110

110

Work Order ID: 60443

Parent Item:

D900-619-011

Parent Item Name: Bearpaw

59108

D2274

D2421

D2529

Sy Washer

Bearpaw, 900 D2519

Manufactured No

Manufactured

Manufactured

Manufactured

Each

357 137

220

Each

Each

Loc Qty

Start Date: 7/8/2010

Required Date: 7/15/2010

Start Qty: 4.00 3

Required Oty: 4.00

357.0000

Loc Code

0.0000

36,0000

Loc Code

338.0000

Location

' Location

ST456

Location

ST010

No

No

No

ST017

58568

56763

Loc Qty 338

338

Loc Oty

36

36

Each

Loc Code

Picklist Print Wednesday, July 07, 2010 3:25:42 PM	Л						i			Page 3
Work Order ID: 60443 Parent Item: D900-619-011		:								
Parent Item Name: Bearpaw		1 1001110 1012 12111 02111 02					art Date: 7		Required D	ate: 7/15/2010 Qty: 4.00
MS21042L4	Purchased	No		110	Each	4,394.000	8	3 2 24	/1/292	/
QS100-M24S Galamp	Purchased	ST356 No Locati ST449	113422 114523 114718 114784 115108 108145		4382 68 28 286 2000 2000 12 12 Each	36.0000 Loc Code	4	27 -+6/2 /0/7/	2712	3
		·						i		
Wednesday, July 07, 2010 3:25:42 Pl	M		Shop P	Packet Print			·		<u>.</u>	Page 3

ICA Page 19 (20 blank) of 20






Figure 32-2: Bearpaw Installation (section view)

- 6. Additional AN960JD416 washers may be installed under the nuts to ensure 1.5-4 threads in safety on the bolts. Although not generally necessary, it is also acceptable to replace the AN4-15A bolts with longer or shorter AN4 bolts, if required.
- 7. Lower the aircraft

32.2 BEARPAW REMOVAL

- 1. Jack up the aircraft.
- 2. Loosen the clamp bolts and remove the bearpaws and clamps. Ensure the skidtubes are serviceable.
- 3. Lower the aircraft.

32.3 WEIGHT AND BALANCE

		LA.	TERAL	LONGITUDINAL		
Installation	Weight	Arm	Moment	Arm	Moment	
D900-619-011 Bearpaw Installation	13.8 lb	0.0 in	0.0 lb-kg	233.3 in	3220 in-lb	
	6.3 kg	0.0 _. m	0.0 m-kg	5.93 m	37.4.m-kg	

32.4 PARTS LIST

Qty	Part Number	Description	
Х	D900-619-011	BEARPAW INSTALLATION	
4	D2182B060	RUBBER CUSHION	
*8_	D2274	RADIUS BLOCK	
2	D2421	BEARPAW	
` 4	D2519	CLAMP	
. 8	D2529	WASHER	·
• •			
8	AN4-15A	BOLT	
- 8	AN960JD416	WASHER	
8 <i>-</i>	MS21042L4	NUT (OR MS21042-4)	
4	QS100M24S	CLAMP	

■ COPYRIGHT © 2001 BY DART AEROSPACE USA, INC ●
THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE USA, INC.